

INSTRUCTION INSTALLATION
INSULATING PIERCING CONNECTOR

PC1 10 - 10

100568886


Creation date: 06/05

Modification date: 09/11

Written by: DS Zhang


Page: 1/1

- 1 Open the connector to the maximum.




- 2 Place the conductor at the center of the connector

Note: for the double insulated cables, remove the upper insulation




- 3 Place the lateral tap conductor into the <<stop>> (other end)



- 4 Tighten the connector with a screw driver to pierce the insulation

Recommended torque for insulation is 1.5 N.m.

Removal: loosen the screw with a screw driver at off line



NEVER REUSABLE AFTER REMOVAL