## Clip-on adapter

can be used in combination with any digital multimeter with a range of 200 mV/2 V alternating current to carry out current measuring. The connection is made directly at the 4 mm input jack on the multimeter.

- $\bullet$  Measurement range: 0 A to 300 A at 1.5%  $\pm$  2 A
- Operating temperature: 0 °C to 50 °C

- Conversion 1 A AC corresponds to 1 mV
- Width of opening max. 28 mm
  - 1 11 1414

